

CASE STUDY


Gas Turbine Shaft Rub

Challenge

EtaPRO® Predictor™ AutoDiagnosis™ triggered while passing through critical speed; vibration within normal limits after start-up.

Details

Inspection revealed improper coupling installation resulting in oil leak with coking increasing shaft profile.



RESULTS

Avoided potential fire and out-of-warranty issues.

EtaPRO®
A Toshiba Group Company