

CASE STUDY


Gas Turbine Blade Damage

Challenge

Compressor blade fault triggered instantaneous AutoDiagnosis™.

Solution

Step change in AS at 9th stage blade passing frequency, (13.8 KHz); overall vibration normal within normal limits.



RESULTS

Avoided potential collateral damage to nearby blades.

EtaPRO®
A Toshiba Group Company