


Fan Bearing Fault

Challenge

Bearing defect in motor bearing triggered AutoDiagnosis™.

Details

Fault predicted to require action in middle of peak heating season.



RESULTS

Inspection resulted in immediate repair decision.